

White Mountain Apache Tribe Environmental Protection Office

Former Maintenance Building
Asbestos Abatement and Demolish
October 2015

Former Maintenance Building




Former Maintenance Building towards the end
- asbestos was mainly in the front area of the
building.




Canyon State Restoration of Mesa, Arizona – contractor selected for the asbestos abatement project.



Inside the building during cleanup of solid waste debris – work completed by Tribal Public Works.



During asbestos abatement



After abatement was complete





During demolish of building
by Tribal Public Works
Department.





The area after the building was removed.

10/23/2015

EPO staff were on-site during the abatement and demolish project.

